







Frame in Dijari





Frame in Dijari





Sill beam in the roof structure in Satkhol between 1900 and 1930




Sill beam in the roof structure in Satkhol between 1900 and 1930




Frame in Dijari between 1954-55




Frame in Dijari between 1954-55







Ständer und Riegel
Verbindung in Dijari



Post connection almost
only between Frame and
post in Dijari



Door and window corner
joint in Sstkhol between
1900 and 1930 build.



Joint of the post
between two
windows or doors in
Satkhol between